MOUNTING PROCEDURE

KIT WINDSHIELD YAMAHA TRACER

YMTR9300

KIT

X1. PLEXIGLASS

X1. PLEXIGLASS
X2. SPECIFIC BRACKET
X2. SCREW "ROUND HEAD" 5X12
X2. SCREW "ROUND HEAD" 5X16
X4. SCREW "ROUND HEAD" 5X20
X4. WASHER IN TEFLON Ø 5


X6. RUBBER WASHER

X4. WASHER Ø 5 LARGE X4. NUT Ø 5 AUTOLOCK

WWW.BARRACUDAMOTO.COM

MOUNTING PROCEDURE:

- REMOVE THE ORIGINAL WINDSHIELD AND LEVERPROTECT AND INSTALL SPECIFIC BRACKET WITH THE 5X20 SCREWS IN TO THE HOLES HIGHLIGHT;
- PUT ALL LIKE ILLUSTRATED SCHEME;
- FIND THE RIGHT POSITION OF WINDSHIELD ON THE BRACKET ALREADY FIXED AND LOCK ALL THE SCREWS



NOTE: DON'T LOCK TOO MUCH TO AVOID PLEXIGLASS BROKEN